Qty:

100 Um:

Each

: WEARPAD

: D35371

: N/A

: C

D3537 REV C

Tuesday, 11/13/2007 1:33:47 PM

User:

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material Due Date

Drawing Number

Project Number

Drawing Revision

Customer

Job Number : 35696

: CU-DAR001 Dart Helicopters Services

Estimate Number 12712

P.O. Number This Issue

Prsht Rev. First Issue

Previous Run

Written By

Comment

Checked & Approved By

Additional Product

Type

: Est Rev:A

New Issue 07-02-14 JLM

: SMALL /MED FAB

Job Number:

Seq. #:

Machine Or Operation:

Description:

1.0

M304S16GA

304/316 .063 Sheet

Comment: Qty.:

7.8750 sf(s) 0.0788 sf(s)/Unit Total:

M304S16GA .063" 304 SS SHEET

Batch:

2.0

WATER JE



Comment: FLOW WATER JET

1-Cut as per Dwg D3537

Dwg Rev:___

IR 07- 11-15

Prog Rev:

2-Deburr if necessary

3.0 QC2


HB 07-11-15

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0 QC8

Comment: SECOND CHECK

5.0 BRAKE NO







NC BRAKE

Comment: NC BRAKE

1-Form as per Dwg D3537 on CNC brake using Jigs DT 8261 and DT 8326.

2-Identify as D3537-1



B

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP		111	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			W.							
			,							
					*					
				*	4.9					
Part No):		PAR #:	Fault Category:	NC	R: Yes	(No) DQ	A: 🔘	Date: _	07/1/30

QA: N/C Closed: ____ Date: _

NCR:			WORK OR	DER NON-CONFORMANC	E (NCR)	à		
		Description of NC		Corrective Action Section B		Verification	Annroyal	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		:	,					
		*						
	4	;		(2)				
						21		
		7						

NOTE: Date & initial all entries

	Sday, 11/13/2 Johnston	007 1:33:47 PM	Proces	s Sheet					
Customer:	CU-DAR001	Dart Helicopters Services		Drawing Name: W	EARPAD			-	
Job Number:	35696			Part Number: D3	35371				
Job Number:									
Seq. #:		r Operation:		Descri			<u> </u>	<u>.</u>	
6.0	LARGE FAB	1 	LARGE FAE	BRICATION RESOURC	E 1		1111		
Comme		FABRICATION RESOUR	Datab						
	Qty A/R	Description 2059B Hardcoat	Batch ~ 106036	0106115	11	~~	. 1	~ 01	(20)
	1-Weld a	s per Dwg D3537 using	Jig DT 8210	m106115	tC	0/	11	29	(129)
		e any weld that penetrate	ed through Wearpad	if necessary					
7.0	QC9		VISUAL WE	LDING INSPECTION			 		
					Δ				
		WELDING INSPECTION			YD	<u> </u>	11-2	9	(120
8.0	QC5		INSPECT W	ORK TO CURRENT S	TEP		l I rl i		_
Comme	ent: INSPECT	T WORK TO CURRENT	STEP		Th.) 07-	11-25	, (125)
9.0	POWDER CO	DATING	POWDER C	OATING			F 1 1 1 1		
			1103642				,		
Comme	ent: POWDER		110200		· 1	110011111111111111111111111111111111111	11181		
		Coat Grey Sandtex (Ref:		<u>'</u>	1	09-1	(~ 6	290	XIZO
10.0	QC3	Harianna (marsa mara)	INSPECT P	OWDER COAT/CHEMI	CAL CONVER	RSION 		12	(30)
					~~			75	
Comme		POWDER COAT/CHE			1///	h/	07	////	24
11.0	PACKAGING	1 (1881 (1883 (1881) 1881) (1881)	PACKAGING	3 RESOURCE #1	10	// - - - - - - - - - - - - - - - - - -		1	
								12	00
Comme	nt: PACKAG	ING RESOURCE #1		_	1		,		
	Identify a Location:	and Stock FP	-17	M		0	7/1/	1/2	C
12.0	QC21		FINAL INSP	ECTION/W/O RELEAS	E		1		
								(130)
Comme	nt: FINAL IN	SPECTION/W/O RELEA	SE			<u> 0 1781 1410 1616 616 </u>	<u> </u>	3001	111/30
Job Completion		818181 (1881 1888) 1888 1888 1888 1888 1888 1888 1888 1888 1888 1888 1888 1888 1888						n N	7-7-
·					ſ	L Th	(l-3	, 0	
					\mathcal{U}	/ L - v			

Form: rorocess

Page 2

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES									
DATE	STEP		P	ROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			·					21				
		Q.	440			· ·						
										<u></u>		
Part No			PAR #:	Fault Category:		NC	R: Yes	No DQ	1[A:	Date:		

QA: N/C Closed: ____ Date: ___

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification							
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector				
						,						
				1								
		6 0										

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	35696
Description: Wearpad	Part Number:	D3537-1
Inspection Dwg: D3537 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
4.250	+/-0.010	4.753)sc			*
3.500	+/-0.010	3.500	×			
1.965	+/-0.010	1.967	×			
2.795	+/-0.010	2,795	*			
3.625	+/-0.010	3.626	*			
0.220 x 0.380	+/-0.010	.236x .386	×		-:	
			(1)			
					-	
						· · · · · · · · · · · · · · · · · · ·
					·.	

Measured by:	Audited by:	Prototype Approval:	N/A
Date: 07-1(-15	Date: 11.15	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	07.03.21	New Issue	KJ/JLM	
В	07.04.27	Dimensions revised per Dwg Rev. B	KJ/JLM	1
С	07.05.28	Dimensions revised per Dwg Rev. C	KJ/JLM	adl







D3537-5 LONGITUDINAL BEND (MADE FROM D3537-1F)




COPYRIGHT @ 2006 BY DART AEROSPACE USA

AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.


07.04.13

SECTION A-A




APPLY 2 LAYERS OF 2059B HARDCOAT WELDS TO WITHIN 0.25 OF WEARPAD ENDS 0.188 TO 0.250 THICK

SECTION B-B



D3537-7 LONGITUDINAL BEND 964 (MADE FROM D3537-3F)



		d-	4	D3537 SHEET 1 OF 1
	CHECK	KED 🚜	APPROVED _	DRAWING NO. REV. C
2	DESIG	CB	DRAWN BY	DART AEROSPACE USA, INC.
	Α		06.11.06	NEW ISSUE
	В		07.03.20	ADD AMS 5513 AND AMS 5524
	С		07.04.13	WIDEN TAB TO 0.380, WELD PATTERN

WEARPAD

D3537-1/-3/-5/-7 WEARPAD NOTES

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 16 GAUGE (0.063 THICK) (REF DART SPEC. M304S16GA)

- 2) BREAK ALL SHARP CORNERS 0.063 MAX
- 3) WELD PER QSI 004
- 4) FINISH: POWDER COAT GREY SANDTEX (4,3.5.6) PER QSI 005 4.3
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 6) ALL DIMENSIONS ARE IN INCHES BOO NOTED

